NOTIFICATION OF DEMOLITION AND RENOVATION

JUD#31 44				was the same of th	53131 - D 64/33	ADEMAN	
Operator Project #	rk	2 1. 2	Date Received	RESI	Notification #		
TYPE OF NOTIFICATION (O Origina	J. P. Pavisad, C. Cana	vallad).		allia y al a R	2016 OCT 25	AM 11: 57	
TYPE OF NOTIFICATION (O-Origina	- 67 3.14 TA TW	THE WEST OF THE REAL PROPERTY.	On On One		AIR COMPL	IANCE BR.	
FACILITY INFORMATION (Identify		ntractor and Oth	er Opera	tor):	aliou	Paran	
OWNER NAME: ACTA Realty Corp					grad		
Address: One State Street Pla					Zip: 10004		
City: New York		State: New York			10		
Contact Name: Sam Saegh			***************************************		Telephone: (2	12) 344-5210	
REMOVAL CONTRACTOR:	Pinnacle Environn	nental Corp.			27.77	A TOTAL CONTRACTOR	
Address:	200 Broad Street						
City:	Carlstadt			NJ	Zip: 0702	Zip: 07072	
Contact Name:	ntact Name: Raymond Kinsella				Telephone: (201) 939-6565		
OTHER CONTRACTOR:							
Address:						304	
City:					Zip:		
Contact Name:			Telephone:				
TYPE OF OPERATION (D-Demo, O-C	ordered Demo, R-Ren	novation, E-Emr.	Renovat	ion): R		-	
IS ASBESTOS PRESENT? (YES NO)	Yes						
FACILITY DESCRIPTION (Include Bui	llding Name, Numbe	er and Floor or Re	oom Nu	nber)			
Building Name:		179,17	HURA.			- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1-	
Address: One State Street F	laza						
City: New York	New York			New York	County: New	York	
Site Location: 28th Floor			.1.			The state of the s	
Building Size: 845,018			# of Floors: 32		Age In Years: 45		
Present Use: Commercial	al			Prior Use:			
Procedure, Including Analytical Metho		sed To Detect The PLM - Polarized	e Presenc	e of Asbestos Materia	al:		
Approximate amount of asbestos, including: 1. Regulated ACM to be removed 2. Category I ACM not removed 3. Category II ACM not removed	RACM to be removed	Nonfriable Asbestos Material not to be removed		Material	Indicate Unit of Measurement Below		
		CATI		CAT II	Joseph Pay	UNIT	
Pipes	Andrew State of the Control of the C		1		LnFt:	Ln M:	
Surface Area	600	HE HOSE WITE	4 17 15		SqFt: x	Sq M:	
Vol. RACM off Facility Component					CuFt:	Cu M:	
Scheduled Dates Asbestos Removal (mm/dd//yy)		Start: 09-14-16(1)On Hold(2)10-17-16 (3)10-19-16(4)10-23-16			Complete: 09-14-17		
Schedules Dates Demo/Renovation (mm/dd/yy)		Start:			Complete:		
Serieumes Dutes Defino, Merioration (mini, au, 33)					A A		

DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND RENOVATION SITE:

HEPA Vacs. MicroTraps (Negative Air Pressure) and amended water will be utilized for emissions control.

HEPA	vacs, Microtraps (Negative An	Fiessu	ile) alla allielidea w	ater will be utilized for entity	SIOID COILDON				
WASTE TRANSI	PORTER #1								
Name:	Tri State Transfer, Inc.								
Address:	1199 Randall Avenue								
City:	Bronx			State: NY	Zip: 10474				
Contact Name:	Jimmy Byrne				Telephone: 718-617-0771				
WASTE TRANS	PORTER #2								
Name:	ATC, Inc. / #3- PCC Construction & Contractors, Inc.								
Address:	2 Moriches Middle Island Road / #3- 200 Broad Street								
City:	Shirley	1	#3- Carlstadt	State: NY / #3 - NJ	Zip: 11967 / #3 - 07072				
Contact Name:	Kenny Smith / #3- Joseph Whelan			m	Telephone: 631-924-5050/#3 -201-939-6565				
WASTE DISPOS	SAL SITE (#1 or #2)								
Name:	Minerva Enterprises, Inc.								
	9000 Minerva Road								
City:	Waynesburg		State: OH	Zip: 44688					
Telephone:	330-866-3435								
IF DEMOLITION	ORDERED BY A GOVERNME	ENT A	GENCY, PLEASE ID	ENTIFY THE AGENCY BE	LOW:				
Name:				Title:					
Authority:									
Date of Order (mm/dd/yy):				Date Ordered to Begin(mm/dd/yy):					
FOR EMERGEN	CY RENOVATIONS								
Date and Hour o	f Emergency(mm/dd/yy):								
Description of the	e Sudden, Unexpected Event:								
il .		4			conchla financial hurdon:				

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLES, PULVERIZED, OR REDUCED TO POWDER. Any ACM which is discovered unexpectedly, or non-friable ACM which becomes crumbled will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal.

I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS. (required 1 year after promulgation)

Signature of Owner/Operator

Date: 08-31-16(1)09-12-16(2)10-11-16(3)10-14-16(4)10-18-16

I certify that the above information is correct.

Signature of Owner/Operator

Date: 08-31-16(1)09-12-16(2)10-11-16(3)10-14-16(4)10-18-16